


USB Driver V1.1 Installation Instruction for
WIN98,WINME,WIN2000,WINXP,VISTA,WINDOWS 7


I. Insert the USB-RS232-CD into CD-ROM in your computer, click two times “PL2303_Prolific_DriverInstaller_v10518” .



II. Click “Next”.



III. Click “Finish”.



IV. Plug “USB-RS232 Converter”

Click “Control Panel”-> “System ”-> “Device Manager”

Check “Prolific USB –to-Serial Comm Port(Com3)”

